



WO# 844175700

Completed Storm Inlet Work Order

Report Date: Monday, April 29, 2019

Page 1 of 3

Work Order#	844175700	Activity: SCF	FLUSH CATCH BASIN/CONNECTION	
Address:	48 ST		Pct: 114	Zip: 11101
Cross Street:	37 AVE			
Compass Direction:			Borough: QUEENS	
Building ID:	0	Block:	Lot:	CMBD: 401
Storm Inlet ID:	CB431602			
Address:	48 ST			
Qualifier:	ON 15 FROM 48TH ST 48TH ST/43RD ST			Map# QI137
Area:	4	4	Sub-Area: 401 QUEENS COMMUNITY BOARD 1	
Location :	Asset Location Comments: ON 15 FROM 48TH ST 48TH ST/43RD ST		District: 844175700	
	ON 15 FROM 48TH ST 48TH ST/43RD ST			
Initiated By:	1026	ABRUSCI, JOHN	Initiated: 07-19-2018 10:50 AM	Scheduled: N/A
Assigned To:	5893	SALERNI, ROBERTO	Service# 186596855	Due: N/A
Authorization:	1177	ANELLO, THOMAS		
Crew:	S2	SEWER- 2 LABORERS		
Maint Type:				
Priority:				
Problem:				Permit#
Project:				Completed: 07-19-2018 11:45 AM
Source:				Out of Service: N
				Potential Service Request: N
WO Responsibility:	SQN	SEWER MAINTENANCE-QUEENS N.		
WO Comments:	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATIONFLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUEINSPECTION COMPLETE 7.19.18 1245 AP Caller Comments for SR #: 186596855.....CREATED FOR THE YARD - INVESTIGATE THE AREA			

Work Order Log History

Log Type	Log Started	Log Ended	Log By	Comments

There are no user logs for this work order

Primary Caller Information

Primary Caller:	DEP, ABRUSI	Call Date: 07-02-2018 05:15 PM
-----------------	-------------	--------------------------------



Report Date: Monday, April 29, 2019

Page 2 of 3

Address:	
Day Phone:	(718)595-5816
Comments:	CREATED FOR THE YARD - INVESTIGATE THE AREA

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request cmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to lt. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#464/593ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVECB#431600, 431601,431603,431604,431606,431607,431608CB #431609,432613,432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTALCB#431602,431605,432614 AND 431499 ARE OPEN CURB PIECECATCH BASINS FOUR (4) IN TOTALCB#431601,431602,431603,431604,431605,431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO)STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLESCB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603,431604,431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFFAND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAYINSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463CLEANED FOUR (4) BASINS TO THE BOTTOMFUNCTIONING OTHERS C.O.B. AT THIS TIMEINSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463REPAIR BASIN NO.431608 AT 48 ST AND 37 AVEREMOVE ASPHALT AND OLD CASTING INSIDE UNITNO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORKINSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATERINSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM



Report Date: Monday, April 29, 2019

Page 3 of 3

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334BOLOGNA TRK#464CLEANED BASIN NO.431605 TO THE BOTTOM FUNCTIONINGNO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M.INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464CLEANED BASIN NO.431604 TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATIONFLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUEINSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABSVACTORED M/H#4015054-TO-M/H#4018279 850 FTNO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOTNEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTIONINSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50SUPV: G. PETRUSO TR# 315CREW: SCHWEIZER/FANA TR# 004SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/ONORTHERN BLVD B/T 42 ST & 44 STNO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: There are no Safety Messages for this asset's Activity Code

Asset Safety Messages: There are no Safety Messages for this asset



WO# 844175702

Completed Storm Inlet Work Order

Report Date: Monday, April 29, 2019

Page 1 of 3

Work Order#	844175702	Activity: SCF	FLUSH CATCH BASIN/CONNECTION	
Address:	48 ST	Pct: 114	Zip: 11101	
Cross Street:	37 AVE			
Compass Direction:	Borough: QUEENS			
Building ID:	0	Block:	Lot:	CMBD: 401
Storm Inlet ID:	CB431601			
Address:	48 ST			
Qualifier:	ON 20 FROM 37TH AV 37TH AV/NORTHERN BL		Map# Q1137	
Area:	4	4	Sub-Area: 401 QUEENS COMMUNITY BOARD 1	
Location :	Asset Location Comments: ON15 FROM 48TH ST48TH ST/43RD STON15 FROM 48TH ST48TH ST/43RD ST		District: 844175702	
Initiated By:	1026	ABRUSCI, JOHN	Initiated: 07-19-2018 10:50 AM	Scheduled: N/A
Assigned To:	5893	SALERNI, ROBERTO	Service# 186596855	Due: N/A
Authorization:	1177	ANELLO, THOMAS		
Crew:	S2	SEWER- 2 LABORERS		
Maint Type:				
Priority:				
Problem:	Permit#			
Project:	Completed: 07-19-2018 11:45 AM			
Source:	Out of Service: N			
	Potential Service Request: N			
WO Responsibility:	SQN	SEWER MAINTENANCE-QUEENS N.		
WO Comments:	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATIONFLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUEINSPECTION COMPLETE 7.19.18 1245 APCaller Comments for SR #: 186596855.....CREATED FOR THE YARD - INVESTIGATE THE AREA			
Work Order Log History				
Log Type	Log Started	Log Ended	Log By	Comments
There are no user logs for this work order				
Primary Caller Information				
Primary Caller:	DEP, ABRUSI		Call Date: 07-02-2018 05:15 PM	
Address:				
Day Phone:	(718)595-5816			
Comments:	CREATED FOR THE YARD - INVESTIGATE THE AREA			



Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261 During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request cmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to it. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES 07/03/2018 0800-1205 YAP VEH#261 FURCI-BULLOCK-THOMAS TRK#464/593 ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVE CB#431600, 431601, 431603, 431604, 431606, 431607, 431608 CB #431609, 432613, 432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTAL CB#431602, 431605, 432614 AND 431499 ARE OPEN CURB PIECE CATCH BASINS FOUR (4) IN TOTAL CB#431601, 431602, 431603, 431604, 431605, 431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO) STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLES CB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261 FURCI-BULLOCK-THOMAS TRK#593/464 CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATER AND CLEAN AND CLEAR CB CONN NO. 431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUE INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261 FURCI-BULLOCK-THOMAS TRK#593/464 CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603, 431604, 431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFF AND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAY INSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463 CLEANED FOUR (4) BASINS TO THE BOTTOM FUNCTIONING OTHERS C.O.B. AT THIS TIME INSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463 REPAIR BASIN NO. 431608 AT 48 ST AND 37 AVE REMOVE ASPHALT AND OLD CASTING INSIDE UNIT NO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORK INSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804 CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATER INSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334 BOLOGNA TRK#464 CLEANED BASIN NO. 431605 TO THE BOTTOM FUNCTIONING NO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M. INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464 CLEANED BASIN NO. 431604 TO THE BOTTOM FUNCTIONING INSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM



Report Date: Monday, April 29, 2019

Page 3 of 3

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATIONFLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUEINSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABSVACTORED M/H#4015054-TO-M/H#4018279 850 FTNO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOTNEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTIONINSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50SUPV: G. PETRUSO TR# 315CREW: SCHWEIZER/FANA TR# 004SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/O NORTHERN BLVD B/T 42 ST & 44 STNO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: There are no Safety Messages for this asset's Activity Code

Asset Safety Messages: There are no Safety Messages for this asset



WO# 844175703

Completed Storm Inlet Work Order

Report Date: Monday, April 29, 2019

Page 1 of 3

Work Order#	844175703	Activity: SCF	FLUSH CATCH BASIN/CONNECTION	
Address:	48 ST		Pct: 114	Zip: 11101
Cross Street:	37 AVE			
Compass Direction:			Borough: QUEENS	
Building ID:	0	Block:	Lot:	CMBD: 401
Storm Inlet ID:	CB431607			
Address:	48 ST			
Qualifier:	ON 0 FROM 37TH AV 37TH AV/BARNETT AV			Map# QI137
Area:	4	4	Sub-Area: 401 QUEENS COMMUNITY BOARD 1	
Location :	Asset Location Comments: ON15 FROM 48TH ST48TH ST/43RD STON15 FROM 48TH ST48TH ST/43RD ST		District: 844175703	
Initiated By:	1026	ABRUSCI, JOHN	Initiated: 07-19-2018 10:50 AM	Scheduled: N/A
Assigned To:	5893	SALERNI, ROBERTO	Service# 186596855	Due: N/A
Authorization:	1177	ANELLO, THOMAS		
Crew:	S2	SEWER- 2 LABORERS		
Maint Type:				
Priority:				
Problem:			Permit#	
Project:			Completed: 07-19-2018 11:45 AM	
Source:			Out of Service: N	
			Potential Service Request: N	
WO Responsibility:	SQN	SEWER MAINTENANCE-QUEENS N.		
WO Comments:	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATIONFLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUEINSPECTION COMPLETE 7.19.18 1245 APCaller Comments for SR #: 186596855.....CREATED FOR THE YARD - INVESTIGATE THE AREA			
Work Order Log History				
Log Type	Log Started	Log Ended	Log By	Comments
There are no user logs for this work order				
Primary Caller Information				
Primary Caller:	DEP, ABRUSI		Call Date: 07-02-2018 05:15 PM	
Address:				
Day Phone:	(718)595-5816			
Comments:	CREATED FOR THE YARD - INVESTIGATE THE AREA			



Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261 During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request cmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to it. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES 07/03/2018 0800-1205 YAP VEH#261 FURCI-BULLOCK-THOMAS TRK#464/593 ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVE CB#431600, 431601, 431603, 431604, 431606, 431607, 431608 CB #431609, 432613, 432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTAL CB#431602, 431605, 432614 AND 431499 ARE OPEN CURB PIECE CATCH BASINS FOUR (4) IN TOTAL CB#431601, 431602, 431603, 431604, 431605, 431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO) STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLES CB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261 FURCI-BULLOCK-THOMAS TRK#593/464 CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATER AND CLEAN AND CLEAR CB CONN NO. 431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUE INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261 FURCI-BULLOCK-THOMAS TRK#593/464 CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603, 431604, 431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFF AND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAY INSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463 CLEANED FOUR (4) BASINS TO THE BOTTOM FUNCTIONING OTHERS C.O.B. AT THIS TIME INSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463 REPAIR BASIN NO. 431608 AT 48 ST AND 37 AVE REMOVE ASPHALT AND OLD CASTING INSIDE UNIT NO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORK INSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804 CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATER INSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334 BOLOGNA TRK#464 CLEANED BASIN NO. 431605 TO THE BOTTOM FUNCTIONING NO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M. INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464 CLEANED BASIN NO. 431604 TO THE BOTTOM FUNCTIONING INSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM



Report Date: Monday, April 29, 2019

Page 3 of 3

Custody History				
Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONING INSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATION FLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUE INSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABS VACTORED M/H#4015054-TO-M/H#4018279 850 FT NO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOT NEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTION INSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50 SUPV: G. PETRUSO TR# 315 CREW: SCHWEIZER/FANA TR# 004 SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/O NORTHERN BLVD B/T 42 ST & 44 ST NO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: There are no Safety Messages for this asset's Activity Code

Asset Safety Messages: There are no Safety Messages for this asset



WO# 844178537

Completed Sewer Main Work Order

Report Date: Tuesday, April 30, 2019

Page 1 of 3

Work Order#	844178537	Activity: SVAC	VACTOR SEWER
Address:	48 ST	Pct: 114	Zip: 11101
Cross Street:	37 AVE		
Compass Direction:		Borough: QUEENS	
Building ID:	0	Block:	Lot: CMBD: 401
Sewer Main ID:	401		
Qualifier:		Map#	
Area:	4	Sub-Area: 401 QUEENS COMMUNITY BOARD 1	
Location :		District: 844178537	
Initiated By:	4377	MARINELLI, JOSEPH	Initiated: 07-24-2018 06:59 AM
Assigned To:	4377	MARINELLI, JOSEPH	Scheduled: N/A
			Service# 186596855
			Due: N/A
Authorization:	1177	ANELLO, THOMAS	
Crew:	S2	SEWER- 2 LABORERS	
Maint Type:			
Priority:			
Problem:	SSDAR	SEWER DOWN AND RUNNING	Permit#
Project:	SVACTR	VACTOR CONTRACT	Completed: 07-24-2018 03:00 PM
Source:	PCTR	PRIVATE CONTRACTOR	Out of Service: N
			Potential Service Request: N
WO Responsibility:	SQN	SEWER MAINTENANCE-QUEENS N.	
WO Comments:	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABSVACTORED M/H#4015054-TO-M/H#4018279 850 FTNO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOTNEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTIONINSPECTION COMPLETE 7.25.18 0917 AP Caller Comments for SR #: 186596855.....CREATED FOR THE YARD - INVESTIGATE THE AREA		

Work Order Log History

Log Type	Log Started	Log Ended	Log By	Comments
----------	-------------	-----------	--------	----------

There are no user logs for this work order

Primary Caller Information

Primary Caller:	DEP, ABRUSI	Call Date: 07-02-2018 05:15 PM
Address:		
Day Phone:	(718)595-5816	



Comments: CREATED FOR THE YARD - INVESTIGATE THE AREA

Custlog History

Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request cmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to it. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#464/593ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVECB#431600, 431601,431603,431604,431606,431607,431608CB #431609,432613,432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTALCB#431602,431605,432614 AND 431499 ARE OPEN CURB PIECECATCH BASINS FOUR (4) IN TOTALCB#431601,431602,431603,431604,431605,431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO)STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLESCB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603,431604,431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFFAND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAYINSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463CLEANED FOUR (4) BASINS TO THE BOTTOMFUNCTIONING OTHERS C.O.B. AT THIS TIMEINSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463REPAIR BASIN NO.431608 AT 48 ST AND 37 AVEREMOVE ASPHALT AND OLD CASTING INSIDE UNITNO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORKINSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATERINSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334BOLOGNA TRK#464CLEANED BASIN NO.431605 TO THE BOTTOM FUNCTIONINGNO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M.INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM



Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464CLEANED BASIN NO.431604 TO THE BOTTOM FUNCTIONING INSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONING INSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATION FLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUE INSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABS VACTORED M/H#4015054-TO-M/H#4018279 850 FT NO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOT NEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTION INSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50 SUPV: G. PETRUSO TR# 315 CREW: SCHWEIZER/FANA TR# 004 SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/O NORTHERN BLVD B/T 42 ST & 44 ST NO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: There are no Safety Messages for this asset's Activity Code

Asset Safety Messages: There are no Safety Messages for this asset



WO# 844272150

Non-Completed Work Order

Report Date: Tuesday, April 30, 2019

Page 1 of 3

Work Order#	844272150	Activity: SRL	LINE SEWER (CONTRACTOR)	
Address:	48 ST		Pct: 114	Zip: 11101
Cross Street:	37 AVE NORTHERN BLVD			
Compass Direction:			Borough: QUEENS	
Building ID:		Block:	Lot:	CMBD: 401

Unit ID:

Qualifier:	, Side Of , DIST: 1 FT, DIR: ,			Map#
Area:			Sub-Area:	
Location :	48th Street between 37th Avenue and Northern Boulevard		District: 844272150	
Initiated By:	13135	JAIRAM, KEVIN	Initiated: 01-25-2019 10:34 AM	Scheduled: N/A
Assigned To:			Service# 186596855	Due: N/A

Authorization:				
Crew:				
Maint Type:				
Priority:				
Problem:				Permit#
Project:				Completed: N/A
Source:	FO-CMOM	REFERRED BY CMOM		Out of Service: N
				Potential Service Request: N
WO Responsibility:	SEC	SEWER EMERGENCY CONSTRUCTION		

WO Comments: Break in pipe between manhole (M4015767) to manhole (M4015568) Caller Comments for SR #: 186596855.....CREATED FOR THE YARD - INVESTIGATE THE AREA

Work Order Log History

Log Type	Log Started	Log Ended	Log By	Comments

There are no user logs for this work order

Primary Caller Information

Primary Caller:	DEP, ABRUSI	Call Date: 07-02-2018 05:15 PM
Address:		
Day Phone:	(718)595-5816	
Comments:	CREATED FOR THE YARD - INVESTIGATE THE AREA	

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request cmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to it. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#464/593ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVECB#431600, 431601,431603,431604,431606,431607,431608CB #431609,432613,432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTALCB#431602,431605,432614 AND 431499 ARE OPEN CURB PIECECATCH BASINS FOUR (4) IN TOTALCB#431601,431602,431603,431604,431605,431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO)STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLESCB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603,431604,431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFFAND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAYINSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463CLEANED FOUR (4) BASINS TO THE BOTTOMFUNCTIONING OTHERS C.O.B. AT THIS TIMEINSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463REPAIR BASIN NO.431608 AT 48 ST AND 37 AVEREMOVE ASPHALT AND OLD CASTING INSIDE UNITNO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORKINSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATERINSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334BOLOGNA TRK#464CLEANED BASIN NO.431605 TO THE BOTTOM FUNCTIONINGNO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M.INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464CLEANED BASIN NO.431604 TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM



Report Date: Tuesday, April 30, 2019

Page 3 of 3

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATIONFLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUEINSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABSVACTORED M/H#4015054-TO-M/H#4018279 850 FTNO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOTNEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTIONINSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50SUPV: G. PETRUSO TR# 315CREW: SCHWEIZER/FANA TR# 004SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/ONORTHERN BLVD B/T 42 ST & 44 STNO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: There are no Safety Messages for this asset's Activity Code

Asset Safety Messages: There are no Safety Messages for this asset



WO# 844272155

Non-Completed Work Order

Report Date: Tuesday, April 30, 2019

Page 1 of 3

Work Order#	844272155	Activity: SRL	LINE SEWER (CONTRACTOR)	
Address:	NORTHERN BLVD		Pct: 114	Zip: 11101
Cross Street:	46 ST 47 ST			
Compass Direction:			Borough: QUEENS	
Building ID:	0	Block:	Lot:	CMBD: 401
Unit ID:				
Qualifier:	, Side Of , DIST: 1 FT, DIR: ,			Map#
Area:			Sub-Area:	
Location :	S/S of Northern Boulevard between 45th Street and 48th Street		District: 844272155	
Initiated By:	13135	JAIRAM, KEVIN	Initiated: 01-25-2019 10:52 AM	Scheduled: N/A
Assigned To:			Service# 186596855	Due: N/A
Authorization:				
Crew:				
Maint Type:				
Priority:				
Problem:				Permit#
Project:				Completed: N/A
Source:	FO-CMOM	REFERRED BY CMOM	Out of Service: N	
			Potential Service Request: N	
WO Responsibility:	SEC	SEWER EMERGENCY CONSTRUCTION		
WO Comments: Break in pipe between manhole (M4013797) to manhole (M4013798). Caller Comments for SR #: 186596855.....CREATED FOR THE YARD - INVESTIGATE THE AREA				
Work Order Log History				
Log Type	Log Started	Log Ended	Log By	Comments
There are no user logs for this work order				
Primary Caller Information				
Primary Caller:	DEP, ABRUSI			Call Date: 07-02-2018 05:15 PM
Address:				
Day Phone:	(718)595-5816			
Comments:	CREATED FOR THE YARD - INVESTIGATE THE AREA			



Report Date: Tuesday, April 30, 2019

Page 2 of 3

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request cmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to it. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#464/593ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVE CB#431600, 431601,431603,431604,431606,431607,431608CB #431609,432613,432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTALCB#431602,431605,432614 AND 431499 ARE OPEN CURB PIECECATCH BASINS FOUR (4) IN TOTALCB#431601,431602,431603,431604,431605,431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO)STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLESCB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603,431604,431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFFAND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAYINSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463CLEANED FOUR (4) BASINS TO THE BOTTOMFUNCTIONING OTHERS C.O.B. AT THIS TIMEINSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463REPAIR BASIN NO.431608 AT 48 ST AND 37 AVEREMOVE ASPHALT AND OLD CASTING INSIDE UNITNO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORKINSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATERINSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334BOLOGNA TRK#464CLEANED BASIN NO.431605 TO THE BOTTOM FUNCTIONINGNO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M.INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464CLEANED BASIN NO.431604 TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM



Report Date: Tuesday, April 30, 2019

Page 3 of 3

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONING INSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATION FLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUE INSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABS VACTORED M/H#4015054-TO-M/H#4018279 850 FT NO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOT NEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTION INSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50 SUPV: G. PETRUSO TR# 315CREW: SCHWEIZER/FANA TR# 004SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/O NORTHERN BLVD B/T 42 ST & 44 ST NO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: There are no Safety Messages for this asset's Activity Code

Asset Safety Messages: There are no Safety Messages for this asset



WO# 844272160

Non-Completed Storm Inlet Work Order

Report Date: Tuesday, April 30, 2019

Page 1 of 3

Work Order#	844272160	Activity: SA25	REPAIR CONNECTION	
Address:	48 ST		Pct: 108	Zip: 11104
Cross Street:	BARNETT AVE 37 AVE			
Compass Direction:			Borough: QUEENS	
Building ID:	0	Block:	Lot:	CMBD: 402
Storm Inlet ID:	CB432615			
Address:	BARNETT AVE			
Qualifier:	ON 22 FROM 48TH AV 50TH ST/48TH AV			Map# QI137
Area:	4	4	Sub-Area: 402 QUEENS COMMUNITY BOARD 2	
Location :	48th Street between Barnett Avenue and 37th Avenue		District: 844272160	
Initiated By:	13135	JAIRAM, KEVIN	Initiated: 01-25-2019 11:06 AM	Scheduled: N/A
Assigned To:			Service# 186596855	Due: N/A
Authorization:				
Crew:				
Maint Type:				
Priority:				
Problem:				Permit#
Project:				Completed: N/A
Source:	FO-CMOM	REFERRED BY CMOM		Out of Service: N
				Potential Service Request: N
WO Responsibility:	SEC	SEWER EMERGENCY CONSTRUCTION		
WO Comments:	Break in pipe of the following sections: Between (CB432615 and manhole M4015052); Between (CB432613 and M4015052); Between (CB431606 and CB431605); Between (CB431605 and T connection with sewer line); Between (CB431602 and M4015054). Caller Comments for SR #: 186596855.....CREATED FOR THE YARD - INVESTIGATE THE AREA			
Work Order Log History				
Log Type	Log Started	Log Ended	Log By	Comments
There are no user logs for this work order				
Primary Caller Information				
Primary Caller:	DEP, ABRUSI		Call Date: 07-02-2018 05:15 PM	
Address:				
Day Phone:	(718)595-5816			
Comments:	CREATED FOR THE YARD - INVESTIGATE THE AREA			



Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request cmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to it. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#464/593ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVECB#431600, 431601,431603,431604,431606,431607,431608CB #431609,432613,432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTALCB#431602,431605,432614 AND 431499 ARE OPEN CURB PIECECATCH BASINS FOUR (4) IN TOTALCB#431601,431602,431603,431604,431605,431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO)STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLESCB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603,431604,431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFFAND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAYINSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463CLEANED FOUR (4) BASINS TO THE BOTTOMFUNCTIONING OTHERS C.O.B. AT THIS TIMEINSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463REPAIR BASIN NO.431608 AT 48 ST AND 37 AVEREMOVE ASPHALT AND OLD CASTING INSIDE UNITNO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORKINSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATERINSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334BOLOGNA TRK#464CLEANED BASIN NO.431605 TO THE BOTTOM FUNCTIONINGNO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M.INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464CLEANED BASIN NO.431604 TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM



Report Date: Tuesday, April 30, 2019

Page 3 of 3

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONING INSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATION FLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUE INSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABS VACTORED M/H#4015054-TO-M/H#4018279 850 FT NO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOT NEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTION INSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50 SUPV: G. PETRUSO TR# 315 CREW: SCHWEIZER/FANA TR# 004 SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/O NORTHERN BLVD B/T 42 ST & 44 ST NO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: There are no Safety Messages for this asset's Activity Code

Asset Safety Messages: There are no Safety Messages for this asset



WO# 844272169

Non-Completed Work Order

Report Date: Thursday, May 02, 2019

Page 1 of 3

Work Order#	844272169	Activity: SRL	LINE SEWER (CONTRACTOR)	
Address:	37 AVE		Pct: 114	Zip: 11101
Cross Street:	43 ST 48 ST			
Compass Direction:			Borough: QUEENS	
Building ID:	0	Block:	Lot:	CMBD: 401
Unit ID:				
Qualifier:	, Side Of , DIST: 1 FT, DIR: ,			Map#
Area:			Sub-Area:	
Location :	37th Avenue between 43rd Street and 48th Street		District: 844272169	
Initiated By:	13135	JAIRAM, KEVIN	Initiated: 01-25-2019 11:21 AM	Scheduled: N/A
Assigned To:			Service# 186596855	Due: N/A
Authorization:				
Crew:				
Maint Type:				
Priority:				
Problem:				
Project:				
Source:	FO-CMOM	REFERRED BY CMOM	Permit#	
			Completed: N/A	
			Out of Service: N	
			Potential Service Request: N	
WO Responsibility:	SEC	SEWER EMERGENCY CONSTRUCTION		
WO Comments: Break in pipe between manholes (M4023688) and manhole (M4012536). Caller Comments for SR #: 186596855.....CREATED FOR THE YARD - INVESTIGATE THE AREA				
Work Order Log History				
Log Type	Log Started	Log Ended	Log By	Comments
There are no user logs for this work order				
Primary Caller Information				
Primary Caller:	DEP, ABRUSI			Call Date: 07-02-2018 05:15 PM
Address:				
Day Phone:	(718)595-5816			
Comments:	CREATED FOR THE YARD - INVESTIGATE THE AREA			



Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request cmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to it. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#464/593ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVECB#431600, 431601,431603,431604,431606,431607,431608CB #431609,432613,432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTALCB#431602,431605,432614 AND 431499 ARE OPEN CURB PIECECATCH BASINS FOUR (4) IN TOTALCB#431601,431602,431603,431604,431605,431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO)STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLESB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603,431604,431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFFAND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAYINSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463CLEANED FOUR (4) BASINS TO THE BOTTOMFUNCTIONING OTHERS C.O.B. AT THIS TIMEINSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463REPAIR BASIN NO.431608 AT 48 ST AND 37 AVEREMOVE ASPHALT AND OLD CASTING INSIDE UNITNO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORKINSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATERINSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334BOLOGNA TRK#464CLEANED BASIN NO.431605 TO THE BOTTOM FUNCTIONINGNO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M.INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464CLEANED BASIN NO.431604 TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM



Report Date: Thursday, May 02, 2019

Page 3 of 3

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATIONFLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUEINSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABSVACTORED M/H#4015054-TO-M/H#4018279 850 FTNO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOTNEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTIONINSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50SUPV: G. PETRUSO TR# 315CREW: SCHWEIZER/FANA TR# 004SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/ONORTHERN BLVD B/T 42 ST & 44 STNO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: There are no Safety Messages for this asset's Activity Code

Asset Safety Messages: There are no Safety Messages for this asset



WO# 844272188

Non-Completed Work Order

Report Date: Tuesday, April 30, 2019

Page 1 of 3

Work Order#	844272188	Activity: SRL	LINE SEWER (CONTRACTOR)	
Address:	NORTHERN BLVD		Pct: 114	Zip: 11101
Cross Street:	43 ST 44 ST			
Compass Direction:			Borough: QUEENS	
Building ID:	0	Block:	Lot:	CMBD: 401

Unit ID:

Qualifier:	, Side Of , DIST: 1 FT, DIR: ,		Map#
Area:		Sub-Area:	
Location :	S/S of Northern Boulevard between 44th St and 42 Place Line from M401-3993 to M401-3998	District: 844272188	
Initiated By:	13135	JAIRAM, KEVIN	Initiated: 01-25-2019 11:40 AM
Assigned To:			Scheduled: N/A Service# 186596855 Due: N/A

Authorization:			
Crew:			
Maint Type:			
Priority:			
Problem:			Permit#
Project:			Completed: N/A
Source:	FO-CMOM	REFERRED BY CMOM	Out of Service: N
			Potential Service Request: N
WO Responsibility:	SEC	SEWER EMERGENCY CONSTRUCTION	

WO Comments: Break in pipe between manhole (M4013998) and manhole (M4014000). Caller Comments for SR #: 186596855.....CREATED FOR THE YARD - INVESTIGATE THE AREA

Work Order Log History

Log Type	Log Started	Log Ended	Log By	Comments

There are no user logs for this work order

Primary Caller Information

Primary Caller:	DEP, ABRUSI	Call Date: 07-02-2018 05:15 PM
Address:		
Day Phone:	(718)595-5816	
Comments:	CREATED FOR THE YARD - INVESTIGATE THE AREA	



Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261 During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request cmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to it. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES 07/03/2018 0800-1205 YAP VEH#261 FURCI-BULLOCK-THOMAS TRK#464/593 ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVE CB#431600, 431601, 431603, 431604, 431606, 431607, 431608 CB #431609, 432613, 432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTAL CB#431602, 431605, 432614 AND 431499 ARE OPEN CURB PIECE CATCH BASINS FOUR (4) IN TOTAL CB#431601, 431602, 431603, 431604, 431605, 431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO) STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLES CB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261 FURCI-BULLOCK-THOMAS TRK#593/464 CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATER AND CLEAN AND CLEAR CB CONN NO. 431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUE INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261 FURCI-BULLOCK-THOMAS TRK#593/464 CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603, 431604, 431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFF AND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAY INSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463 CLEANED FOUR (4) BASINS TO THE BOTTOM FUNCTIONING OTHERS C.O.B. AT THIS TIME INSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463 REPAIR BASIN NO. 431608 AT 48 ST AND 37 AVE REMOVE ASPHALT AND OLD CASTING INSIDE UNIT NO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORK INSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804 CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATER INSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334 BOLOGNA TRK#464 CLEANED BASIN NO. 431605 TO THE BOTTOM FUNCTIONING NO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M. INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464 CLEANED BASIN NO. 431604 TO THE BOTTOM FUNCTIONING INSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM



Report Date: Tuesday, April 30, 2019

Page 3 of 3

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONING INSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATION FLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUE INSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABSVACTORED M/H#4015054-TO-M/H#4018279 850 FTNO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOT NEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTION INSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50SUPV: G. PETRUSO TR# 315CREW: SCHWEIZER/FANA TR# 004SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/O NORTHERN BLVD B/T 42 ST & 44 ST NO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: There are no Safety Messages for this asset's Activity Code

Asset Safety Messages: There are no Safety Messages for this asset



WO# 844272196

Non-Completed Work Order

Report Date: Tuesday, April 30, 2019

Page 1 of 3

Work Order#	844272196	Activity: SRB	REPAIR SEWER BREAK (CONTRACT.)	
Address:	NORTHERN BLVD	Pct: 114	Zip: 11101	
Cross Street:	42 ST 43 ST			
Compass Direction:	Borough: QUEENS			
Building ID:	0	Block:	Lot:	CMBD: 401
Unit ID:				
Qualifier:	, Side Of , DIST: 1 FT, DIR: ,			Map#
Area:	Sub-Area:			
Location :	Northern Blvd between 44th Street and 42 Street			District: 844272196
Initiated By:	13135	JAIRAM, KEVIN	Initiated: 01-25-2019 12:00 PM	Scheduled: N/A
Assigned To:	Service# 186596855			Due: N/A
Authorization:				
Crew:				
Maint Type:				
Priority:				
Problem:				Permit#
Project:				Completed: N/A
Source:	FO-CMOM	REFERRED BY CMOM	Out of Service: N	
			Potential Service Request: N	
WO Responsibility:	SEC	SEWER EMERGENCY CONSTRUCTION		
WO Comments: Break in pipe between manhole (M4018448) and manhole (M4020082) Caller Comments for SR #: 186596855.....CREATED FOR THE YARD - INVESTIGATE THE AREA				
Work Order Log History				
Log Type	Log Started	Log Ended	Log By	Comments
There are no user logs for this work order				
Primary Caller Information				
Primary Caller:	DEP, ABRUSI			Call Date: 07-02-2018 05:15 PM
Address:				
Day Phone:	(718)595-5816			
Comments:	CREATED FOR THE YARD - INVESTIGATE THE AREA			



Report Date: Tuesday, April 30, 2019

Page 2 of 3

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request cmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to it. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#464/593ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVECB#431600, 431601,431603,431604,431606,431607,431608CB #431609,432613,432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTALCB#431602,431605,432614 AND 431499 ARE OPEN CURB PIECECATCH BASINS FOUR (4) IN TOTALCB#431601,431602,431603,431604,431605,431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO)STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLESCB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603,431604,431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFFAND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAYINSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463CLEANED FOUR (4) BASINS TO THE BOTTOMFUNCTIONING OTHERS C.O.B. AT THIS TIMEINSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463REPAIR BASIN NO.431608 AT 48 ST AND 37 AVEREMOVE ASPHALT AND OLD CASTING INSIDE UNITNO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORKINSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATERINSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334BOLOGNA TRK#464CLEANED BASIN NO.431605 TO THE BOTTOM FUNCTIONINGNO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M.INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464CLEANED BASIN NO.431604 TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM



Report Date: Tuesday, April 30, 2019

Page 3 of 3

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATIONFLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUEINSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABSVACTORED M/H#4015054-TO-M/H#4018279 850 FTNO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOTNEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTIONINSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50SUPV: G. PETRUSO TR# 315CREW: SCHWEIZER/FANA TR# 004SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/ONORTHERN BLVD B/T 42 ST & 44 STNO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: There are no Safety Messages for this asset's Activity Code

Asset Safety Messages: There are no Safety Messages for this asset



WO# 844272206

Completed Water Main Work Order

Report Date: Tuesday, April 30, 2019

Page 1 of 3

Work Order#	844272206	Activity: WLDSC	SCAN WATER MAINS- LEAK DET.	
Address:	NORTHERN BLVD	Pct: 114	Zip: 11101	
Cross Street:	42 ST 43 ST			
Compass Direction:	Borough: QUEENS			
Building ID:	0	Block:	Lot:	CMBD: 401

Water Main ID:

Qualifier:	, Side Of , DIST: 1 FT, DIR: ,	Map#	
Area:		Sub-Area:	
Location :	Northern Boulevard between 44th Street and 42nd Street	District: 844272206	
Initiated By:	13135 JAIRAM, KEVIN	Initiated: 01-25-2019 12:23 PM	Scheduled: N/A
Assigned To:		Service# 186596855	Due: N/A

Authorization:		
Crew:		
Maint Type:		
Priority:		
Problem:		Permit#
Project:		Completed: 02-13-2019 01:50 PM
Source:	FO-CMOM REFERRED BY CMOM	Out of Service: N
		Potential Service Request: N
WO Responsibility:	WMQ WATER MAINT.-QUEENS	

WO Comments: Infiltration runner/dripper between manhole (M4018448) and manhole (M4020082). Infiltration weeper between manhole (M4020082) and manhole (M4020081). Infiltration dripper between manhole (M4020081) and manhole (M4023279). Infiltration weeper between manhole (M4023279) and manhole (M4014002).
Caller Comments for SR #: 186596855.....CREATED FOR THE YARD - INVESTIGATE THE AREA

Work Order Log History

Log Type	Log Started	Log Ended	Log By	Comments

There are no user logs for this work order

Primary Caller Information

Primary Caller:	DEP, ABRUSI	Call Date: 07-02-2018 05:15 PM
Address:		
Day Phone:	(718)595-5816	
Comments:	CREATED FOR THE YARD - INVESTIGATE THE AREA	



Report Date: Tuesday, April 30, 2019

Page 2 of 3

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request cmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to it. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#464/593ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVECB#431600, 431601,431603,431604,431606,431607,431608CB #431609,432613,432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTALCB#431602,431605,432614 AND 431499 ARE OPEN CURB PIECECATCH BASINS FOUR (4) IN TOTALCB#431601,431602,431603,431604,431605,431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO)STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLESCB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603,431604,431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFFAND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAYINSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463CLEANED FOUR (4) BASINS TO THE BOTTOMFUNCTIONING OTHERS C.O.B. AT THIS TIMEINSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463REPAIR BASIN NO.431608 AT 48 ST AND 37 AVEREMOVE ASPHALT AND OLD CASTING INSIDE UNITNO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORKINSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATERINSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334BOLOGNA TRK#464CLEANED BASIN NO.431605 TO THE BOTTOM FUNCTIONINGNO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M.INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464CLEANED BASIN NO.431604 TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM



Report Date: Tuesday, April 30, 2019

Page 3 of 3

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONING INSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATION FLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUE INSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABS VACTORED M/H#4015054-TO-M/H#4018279 850 FT NO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOT NEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTION INSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50 SUPV: G. PETRUSO TR# 315 CREW: SCHWEIZER/FANA TR# 004 SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/O NORTHERN BLVD B/T 42 ST & 44 ST NO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: There are no Safety Messages for this asset's Activity Code

Asset Safety Messages: There are no Safety Messages for this asset



WO# 844272213

Completed Water Main Work Order

Report Date: Tuesday, April 30, 2019

Page 1 of 3

Work Order#	844272213	Activity: WLDSC	SCAN WATER MAINS- LEAK DET.	
Address:	NORTHERN BLVD	Pct: 114	Zip: 11101	
Cross Street:	43 ST 44 ST			
Compass Direction:	Borough: QUEENS			
Building ID:	0	Block:	Lot:	CMBD: 401
Water Main ID:				
Qualifier:	, Side Of , DIST: 1 FT, DIR: ,		Map#	
Area:			Sub-Area:	
Location :	Northern Boulevard between 44th Street and 43rd Street		District: 844272213	
Initiated By:	13135	JAIRAM, KEVIN	Initiated: 01-25-2019 12:31 PM	Scheduled: N/A
Assigned To:			Service# 186596855	Due: N/A
Authorization:				
Crew:				
Maint Type:				
Priority:				
Problem:	Permit#			
Project:	Completed: 02-13-2019 01:50 PM			
Source:	FO-CMOM	REFERRED BY CMOM	Out of Service: N	
			Potential Service Request: N	
WO Responsibility:	WMQ	WATER MAINT.-QUEENS		
WO Comments: Infiltration runner between manhole (M4013999) and manhole (M4014000). Infiltration dripper/weeper/runner between manhole (4014000) and manhole (4014001). Caller Comments for SR #: 186596855.....CREATED FOR THE YARD - INVESTIGATE THE AREA				
Work Order Log History				
Log Type	Log Started	Log Ended	Log By	Comments
There are no user logs for this work order				
Primary Caller Information				
Primary Caller:	DEP, ABRUSI		Call Date: 07-02-2018 05:15 PM	
Address:				
Day Phone:	(718)595-5816			
Comments:	CREATED FOR THE YARD - INVESTIGATE THE AREA			



Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request crmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to it. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#464/593ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVECB#431600, 431601,431603,431604,431606,431607,431608CB #431609,432613,432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTALCB#431602,431605,432614 AND 431499 ARE OPEN CURB PIECECATCH BASINS FOUR (4) IN TOTALCB#431601,431602,431603,431604,431605,431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO)STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLESCB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603,431604,431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFFAND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAYINSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463CLEANED FOUR (4) BASINS TO THE BOTTOMFUNCTIONING OTHERS C.O.B. AT THIS TIMEINSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463REPAIR BASIN NO.431608 AT 48 ST AND 37 AVEREMOVE ASPHALT AND OLD CASTING INSIDE UNITNO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORKINSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATERINSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334BOLOGNA TRK#464CLEANED BASIN NO.431605 TO THE BOTTOM FUNCTIONINGNO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M.INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464CLEANED BASIN NO.431604 TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM



Report Date: Tuesday, April 30, 2019

Page 3 of 3

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATIONFLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUEINSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABSVACTORED M/H#4015054-TO-M/H#4018279 850 FTNO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOTNEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTIONINSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50SUPV: G. PETRUSO TR# 315CREW: SCHWEIZER/FANA TR# 004SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/ONORTHERN BLVD B/T 42 ST & 44 STNO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: There are no Safety Messages for this asset's Activity Code

Asset Safety Messages: There are no Safety Messages for this asset



WO# 844274546

Non-Completed Work Order

Report Date: Tuesday, April 30, 2019

Page 1 of 3

Work Order#	844274546	Activity: SMREPR	REPAIR SWR MANHOLE (CONTRACT.)	
Address:	NORTHERN BLVD	Pct: 114	Zip: 11101	
Cross Street:	43 ST 44 ST			
Compass Direction:	Borough: QUEENS			
Building ID:	0	Block:	Lot:	CMBD: 401
Unit ID:				
Qualifier:	, Side Of , DIST: 1 FT, DIR: ,			Map#
Area:	Sub-Area:			
Location :	Northern Boulevard between 42nd Pl and 44th Street		District: 844274546	
Initiated By:	13135	JAIRAM, KEVIN	Initiated: 01-30-2019 01:47 PM	Scheduled: N/A
Assigned To:			Service# 186596855	Due: N/A
Authorization:				
Crew:				
Maint Type:				
Priority:				
Problem:				Permit#
Project:				Completed: N/A
Source:	FO-CMOM	REFERRED BY CMOM	Out of Service: N	
			Potential Service Request: N	
WO Responsibility:	WMQ	WATER MAINT.-QUEENS		
WO Comments:	The following manholes need repair: M4013998, M4013992, M4013993. Caller Comments for SR #: 186596855.....CREATED FOR THE YARD - INVESTIGATE THE AREA			
Work Order Log History				
Log Type	Log Started	Log Ended	Log By	Comments
There are no user logs for this work order				
Primary Caller Information				
Primary Caller:	DEP, ABRUSI			Call Date: 07-02-2018 05:15 PM
Address:				
Day Phone:	(718)595-5816			
Comments:	CREATED FOR THE YARD - INVESTIGATE THE AREA			



Report Date: Tuesday, April 30, 2019

Page 2 of 3

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request cmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to it. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#464/593ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVECB#431600, 431601,431603,431604,431606,431607,431608CB #431609,432613,432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTALCB#431602,431605,432614 AND 431499 ARE OPEN CURB PIECECATCH BASINS FOUR (4) IN TOTALCB#431601,431602,431603,431604,431605,431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO)STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLES CB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603,431604,431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFFAND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAYINSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463CLEANED FOUR (4) BASINS TO THE BOTTOMFUNCTIONING OTHERS C.O.B. AT THIS TIMEINSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463REPAIR BASIN NO.431608 AT 48 ST AND 37 AVEREMOVE ASPHALT AND OLD CASTING INSIDE UNITNO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORKINSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATERINSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334BOLOGNA TRK#464CLEANED BASIN NO.431605 TO THE BOTTOM FUNCTIONINGNO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M.INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464CLEANED BASIN NO.431604 TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM



Report Date: Tuesday, April 30, 2019

Page 3 of 3

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATIONFLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUEINSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABSVACTORED M/H#4015054-TO-M/H#4018279 850 FTNO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOTNEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTIONINSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50SUPV: G. PETRUSO TR# 315CREW: SCHWEIZER/FANA TR# 004SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/ONORTHERN BLVD B/T 42 ST & 44 STNO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: There are no Safety Messages for this asset's Activity Code

Asset Safety Messages: There are no Safety Messages for this asset



WO# 844279306

Non-Completed Storm Inlet Work Order

Report Date: Tuesday, April 30, 2019

Page 1 of 3

Work Order#	844279306	Activity: SA25	REPAIR CONNECTION	
Address:	48 ST		Pct: 114	Zip: 11101
Cross Street:	37 AVE			
Compass Direction:			Borough: QUEENS	
Building ID:	0	Block:	Lot:	CMBD: 401
Storm Inlet ID:	CB431602			
Address:	48 ST			
Qualifier:	ON 15 FROM 48TH ST 48TH ST/43RD ST			Map# QI137
Area:	4	4	Sub-Area: 401 QUEENS COMMUNITY BOARD 1	
Location :	Asset Location Comments: ON 15 FROM 48TH ST 48TH ST/43RD ST		District: 844279306	
	ON 15 FROM 48TH ST 48TH ST/43RD ST			
Initiated By:	1193	ANZUETA, JOSEPH	Initiated: 02-07-2019 10:10 AM	Scheduled: N/A
Assigned To:			Service# 186596855	Due: N/A
Authorization:				
Crew:				
Maint Type:				
Priority:				
Problem:				Permit#
Project:				Completed: N/A
Source:				Out of Service: N
				Potential Service Request: N
WO Responsibility:	SEC	SEWER EMERGENCY CONSTRUCTION		

WO Comments:

Caller Comments for SR #: 186596855.....CREATED FOR THE YARD - INVESTIGATE THE AREA

Work Order Log History

Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	02-07-2019	02-07-2019	1193- ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction Input By: LINDA BUSH on 2/8/2019 8:11:54 AM

There are no user logs for this work order

Primary Caller Information



Report Date: Tuesday, April 30, 2019

Page 2 of 3

Primary Caller:	DEP, ABRUSI	Call Date: 07-02-2018 05:15 PM
Address:		
Day Phone:	(718)595-5816	
Comments:	CREATED FOR THE YARD - INVESTIGATE THE AREA	

Custlog History

Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261 During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request cmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to it. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES 07/03/2018 0800-1205 YAP VEH#261 FURCI-BULLOCK-THOMAS TRK#464/593 ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVE CB#431600, 431601, 431603, 431604, 431606, 431607, 431608 CB #431609, 432613, 432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTAL CB#431602, 431605, 432614 AND 431499 ARE OPEN CURB PIECE CATCH BASINS FOUR (4) IN TOTAL CB#431601, 431602, 431603, 431604, 431605, 431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO) STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLES CB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261 FURCI-BULLOCK-THOMAS TRK#593/464 CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATER AND CLEAN AND CLEAR CB CONN NO. 431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUE INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261 FURCI-BULLOCK-THOMAS TRK#593/464 CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603, 431604, 431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFF AND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAY INSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463 CLEANED FOUR (4) BASINS TO THE BOTTOM FUNCTIONING OTHERS C.O.B. AT THIS TIME INSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463 REPAIR BASIN NO. 431608 AT 48 ST AND 37 AVE REMOVE ASPHALT AND OLD CASTING INSIDE UNIT NO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORK INSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804 CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATER INSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM



Report Date: Tuesday, April 30, 2019

Page 3 of 3

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334BOLOGNA TRK#464CLEANED BASIN NO.431605 TO THE BOTTOM FUNCTIONINGNO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M.INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464CLEANED BASIN NO.431604 TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATIONFLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUEINSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABSVACTORED M/H#4015054-TO-M/H#4018279 850 FTNO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOTNEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTIONINSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50SUPV: G. PETRUSO TR# 315CREW: SCHWEIZER/FANA TR# 004SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/ONORTHERN BLVD B/T 42 ST & 44 STNO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: There are no Safety Messages for this asset's Activity Code

Asset Safety Messages: There are no Safety Messages for this asset



WO# 844326003

Non-Completed Storm Inlet Work Order

Report Date: Tuesday, April 30, 2019

Page 1 of 3

Work Order#	844326003	Activity: SA25	REPAIR CONNECTION	
Address:	48 ST		Pct: 114	Zip: 11101
Cross Street:	37 AVE			
Compass Direction:			Borough: QUEENS	
Building ID:	0	Block:	Lot:	CMBD: 401
Storm Inlet ID:	CB431606			
Address:	48 ST			
Qualifier:	ON 40 FROM 37TH AV BARNETT AV/37TH AV			Map# QI137
Area:	4	4	Sub-Area: 401 QUEENS COMMUNITY BOARD 1	
Location :	Asset Location Comments: ON 40 FROM 37TH AV BARNETT AV/37TH AV		District: 844326003	
	ON 40 FROM 37TH AV BARNETT AV/37TH AV			
Initiated By:	5425	PORCELLO, LOUISE A	Initiated: 04-23-2019 03:30 PM	Scheduled: N/A
Assigned To:			Service# 186596855	Due: N/A
Authorization:				
Crew:				
Maint Type:				
Priority:				
Problem:				Permit#
Project:				Completed: N/A
Source:				Out of Service: N
				Potential Service Request: N
WO Responsibility:	SEC	SEWER EMERGENCY CONSTRUCTION		

Work Order Log History				
Log Type	Log Started	Log Ended	Log By	Comments

There are no user logs for this work order

Primary Caller Information	
Primary Caller:	DEP, ABRUSI
Address:	
Day Phone:	(718)595-5816
Comments:	CREATED FOR THE YARD - INVESTIGATE THE AREA
	Call Date: 07-02-2018 05:15 PM



Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request cmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to it. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#464/593ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVECB#431600, 431601,431603,431604,431606,431607,431608CB #431609,432613,432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTALCB#431602,431605,432614 AND 431499 ARE OPEN CURB PIECECATCH BASINS FOUR (4) IN TOTALCB#431601,431602,431603,431604,431605,431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO)STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLESCB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603,431604,431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFFAND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAYINSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463CLEANED FOUR (4) BASINS TO THE BOTTOMFUNCTIONING OTHERS C.O.B. AT THIS TIMEINSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463REPAIR BASIN NO.431608 AT 48 ST AND 37 AVEREMOVE ASPHALT AND OLD CASTING INSIDE UNITNO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORKINSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATERINSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334BOLOGNA TRK#464CLEANED BASIN NO.431605 TO THE BOTTOM FUNCTIONINGNO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M.INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464CLEANED BASIN NO.431604 TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM



Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATIONFLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUEINSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABSVACTORED M/H#4015054-TO-M/H#4018279 850 FTNO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOTNEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTIONINSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50SUPV: G. PETRUSO TR# 315CREW: SCHWEIZER/FANA TR# 004SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/ONORTHERN BLVD B/T 42 ST & 44 STNO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: There are no Safety Messages for this asset's Activity Code

Asset Safety Messages: There are no Safety Messages for this asset



WO# 844326019

Non-Completed Storm Inlet Work Order

Report Date: Tuesday, April 30, 2019

Page 1 of 3

Work Order#	844326019	Activity: SA25	REPAIR CONNECTION	
Address:	48 ST		Pct: 114	Zip: 11101
Cross Street:	37 AVE			
Compass Direction:			Borough: QUEENS	
Building ID:	0	Block:	Lot:	CMBD: 401
Storm Inlet ID:	CB431605			
Address:	48 ST			
Qualifier:	ON 40 FROM 37TH AV 37TH AV/BARNETT AV			Map# QI137
Area:	4	4	Sub-Area: 401 QUEENS COMMUNITY BOARD 1	
Location :	Asset Location Comments: ON 40 FROM 37TH AV 37TH AV/BARNETT AV		District: 844326019	
	ON 40 FROM 37TH AV 37TH AV/BARNETT AV			
Initiated By:	5425	PORCELLO, LOUISE A	Initiated: 04-23-2019 03:41 PM	Scheduled: N/A
Assigned To:			Service# 186596855	Due: N/A
Authorization:				
Crew:				
Maint Type:				
Priority:				
Problem:				Permit#
Project:				Completed: N/A
Source:				Out of Service: N
				Potential Service Request: N
WO Responsibility:	SEC	SEWER EMERGENCY CONSTRUCTION		

Work Order Log History				
Log Type	Log Started	Log Ended	Log By	Comments

There are no user logs for this work order

Primary Caller Information	
Primary Caller:	DEP, ABRUSI
Address:	
Day Phone:	(718)595-5816
Comments:	CREATED FOR THE YARD - INVESTIGATE THE AREA

Call Date: 07-02-2018 05:15 PM

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request cmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to it. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#464/593ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVECB#431600, 431601,431603,431604,431606,431607,431608CB #431609,432613,432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTALCB#431602,431605,432614 AND 431499 ARE OPEN CURB PIECECATCH BASINS FOUR (4) IN TOTALCB#431601,431602,431603,431604,431605,431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO)STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLESCB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603,431604,431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFFAND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAYINSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463CLEANED FOUR (4) BASINS TO THE BOTTOMFUNCTIONING OTHERS C.O.B. AT THIS TIMEINSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463REPAIR BASIN NO.431608 AT 48 ST AND 37 AVEREMOVE ASPHALT AND OLD CASTING INSIDE UNITNO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORKINSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATERINSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334BOLOGNA TRK#464CLEANED BASIN NO.431605 TO THE BOTTOM FUNCTIONINGNO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M.INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464CLEANED BASIN NO.431604 TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM



Report Date: Tuesday, April 30, 2019

Page 3 of 3

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONING INSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATION FLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUE INSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABS VACTORED M/H#4015054-TO-M/H#4018279 850 FT NO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOT NEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTION INSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50 SUPV: G. PETRUSO TR# 315 CREW: SCHWEIZER/FANA TR# 004 SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/O NORTHERN BLVD B/T 42 ST & 44 ST NO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: There are no Safety Messages for this asset's Activity Code

Asset Safety Messages: There are no Safety Messages for this asset



WO# 844326023

Non-Completed Storm Inlet Work Order

Report Date: Tuesday, April 30, 2019

Page 1 of 3

Work Order#	844326023	Activity: SA25	REPAIR CONNECTION	
Address:	48 ST		Pct: 114	Zip: 11101
Cross Street:	37 AVE			
Compass Direction:			Borough: QUEENS	
Building ID:	0	Block:	Lot:	CMBD: 401
Storm Inlet ID:	CB431604			
Address:	48 ST			
Qualifier:	ON 15 FROM 37TH AV 37TH AV/BARNETT AV			Map# QI137
Area:	4	4	Sub-Area: 401 QUEENS COMMUNITY BOARD 1	
Location :	Asset Location Comments: ON 15 FROM 37TH AV 37TH AV/BARNETT AV		District: 844326023	
	ON 15 FROM 37TH AV 37TH AV/BARNETT AV			
Initiated By:	5425	PORCELLO, LOUISE A	Initiated: 04-23-2019 03:47 PM	Scheduled: N/A
Assigned To:			Service# 186596855	Due: N/A
Authorization:				
Crew:				
Maint Type:				
Priority:				
Problem:				Permit#
Project:				Completed: N/A
Source:				Out of Service: N
				Potential Service Request: N
WO Responsibility:	SEC	SEWER EMERGENCY CONSTRUCTION		

Work Order Log History

Log Type	Log Started	Log Ended	Log By	Comments

There are no user logs for this work order

Primary Caller Information

Primary Caller:	DEP, ABRUSI	Call Date: 07-02-2018 05:15 PM
Address:		
Day Phone:	(718)595-5816	
Comments:	CREATED FOR THE YARD - INVESTIGATE THE AREA	

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request cmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to it. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#464/593ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVECB#431600, 431601,431603,431604,431606,431607,431608CB #431609,432613,432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTALCB#431602,431605,432614 AND 431499 ARE OPEN CURB PIECECATCH BASINS FOUR (4) IN TOTALCB#431601,431602,431603,431604,431605,431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO)STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLESCB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603,431604,431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFFAND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAYINSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463CLEANED FOUR (4) BASINS TO THE BOTTOMFUNCTIONING OTHERS C.O.B. AT THIS TIMEINSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463REPAIR BASIN NO.431608 AT 48 ST AND 37 AVEREMOVE ASPHALT AND OLD CASTING INSIDE UNITNO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORKINSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATERINSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334BOLOGNA TRK#464CLEANED BASIN NO.431605 TO THE BOTTOM FUNCTIONINGNO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M.INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464CLEANED BASIN NO.431604 TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM



Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONING INSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATION FLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUE INSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABS VACTORED M/H#4015054-TO-M/H#4018279 850 FT NO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOT NEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTION INSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50 SUPV: G. PETRUSO TR# 315CREW: SCHWEIZER/FANA TR# 004SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/O NORTHERN BLVD B/T 42 ST & 44 ST NO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: There are no Safety Messages for this asset's Activity Code

Asset Safety Messages: There are no Safety Messages for this asset



WO# 844326026

Non-Completed Storm Inlet Work Order

Report Date: Tuesday, April 30, 2019

Page 1 of 3

Work Order#	844326026	Activity: SA25	REPAIR CONNECTION	
Address:	48 ST		Pct: 114	Zip: 11101
Cross Street:	37 AVE			
Compass Direction:			Borough: QUEENS	
Building ID:	0	Block:	Lot:	CMBD: 401
Storm Inlet ID:	CB431603			
Address:	48 ST			
Qualifier:	ON 20 FROM 48TH ST 48TH ST/43RD ST			Map# QI137
Area:	4	4	Sub-Area: 401 QUEENS COMMUNITY BOARD 1	
Location :	Asset Location Comments: ON 20 FROM 48TH ST 48TH ST/43RD ST		District: 844326026	
	ON 20 FROM 48TH ST 48TH ST/43RD ST			
Initiated By:	5425	PORCELLO, LOUISE A	Initiated: 04-23-2019 03:49 PM	Scheduled: N/A
Assigned To:			Service# 186596855	Due: N/A
Authorization:				
Crew:				
Maint Type:				
Priority:				
Problem:				Permit#
Project:				Completed: N/A
Source:				Out of Service: N
				Potential Service Request: N
WO Responsibility:	SEC	SEWER EMERGENCY CONSTRUCTION		

Work Order Log History

Log Type	Log Started	Log Ended	Log By	Comments

There are no user logs for this work order

Primary Caller Information

Primary Caller:	DEP, ABRUSI	Call Date: 07-02-2018 05:15 PM
Address:		
Day Phone:	(718)595-5816	
Comments:	CREATED FOR THE YARD - INVESTIGATE THE AREA	



Report Date: Tuesday, April 30, 2019

Page 2 of 3

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261 During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request cmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to it. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES 07/03/2018 0800-1205 YAP VEH#261 FURCI-BULLOCK-THOMAS TRK#464/593 ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVE CB#431600, 431601, 431603, 431604, 431606, 431607, 431608 CB #431609, 432613, 432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTAL CB#431602, 431605, 432614 AND 431499 ARE OPEN CURB PIECE CATCH BASINS FOUR (4) IN TOTAL CB#431601, 431602, 431603, 431604, 431605, 431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO) STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLES CB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261 FURCI-BULLOCK-THOMAS TRK#593/464 CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATER AND CLEAN AND CLEAR CB CONN NO. 431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUE INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261 FURCI-BULLOCK-THOMAS TRK#593/464 CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603, 431604, 431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFF AND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAY INSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463 CLEANED FOUR (4) BASINS TO THE BOTTOM FUNCTIONING OTHERS C.O.B. AT THIS TIME INSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463 REPAIR BASIN NO. 431608 AT 48 ST AND 37 AVE REMOVE ASPHALT AND OLD CASTING INSIDE UNIT NO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORK INSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804 CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATER INSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334 BOLOGNA TRK#464 CLEANED BASIN NO. 431605 TO THE BOTTOM FUNCTIONING NO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M. INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464 CLEANED BASIN NO. 431604 TO THE BOTTOM FUNCTIONING INSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM



Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATIONFLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUEINSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABSVACTORED M/H#4015054-TO-M/H#4018279 850 FTNO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOTNEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTIONINSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50SUPV: G. PETRUSO TR# 315CREW: SCHWEIZER/FANA TR# 004SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/ONORTHERN BLVD B/T 42 ST & 44 STNO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: There are no Safety Messages for this asset's Activity Code

Asset Safety Messages: There are no Safety Messages for this asset



WO# 844326027

Non-Completed Storm Inlet Work Order

Report Date: Tuesday, April 30, 2019

Page 1 of 3

Work Order#	844326027	Activity: SA25	REPAIR CONNECTION	
Address:	48 ST		Pct: 114	Zip: 11101
Cross Street:	37 AVE			
Compass Direction:			Borough: QUEENS	
Building ID:	0	Block:	Lot:	CMBD: 401
Storm Inlet ID:	CB431602			
Address:	48 ST			
Qualifier:	ON 15 FROM 48TH ST 48TH ST/43RD ST			Map# QI137
Area:	4	4	Sub-Area: 401 QUEENS COMMUNITY BOARD 1	
Location :	Asset Location Comments: ON 15 FROM 48TH ST 48TH ST/43RD ST		District: 844326027	
	ON 15 FROM 48TH ST 48TH ST/43RD ST			
Initiated By:	5425	PORCELLO, LOUISE A	Initiated: 04-23-2019 03:50 PM	Scheduled: N/A
Assigned To:			Service# 186596855	Due: N/A
Authorization:				
Crew:				
Maint Type:				
Priority:				
Problem:				Permit#
Project:				Completed: N/A
Source:				Out of Service: N
				Potential Service Request: N
WO Responsibility:	SEC	SEWER EMERGENCY CONSTRUCTION		

Work Order Log History

Log Type	Log Started	Log Ended	Log By	Comments

There are no user logs for this work order

Primary Caller Information

Primary Caller:	DEP, ABRUSI	Call Date: 07-02-2018 05:15 PM
Address:		
Day Phone:	(718)595-5816	
Comments:	CREATED FOR THE YARD - INVESTIGATE THE AREA	



Report Date: Tuesday, April 30, 2019

Page 2 of 3

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request cmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to it. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#464/593ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVECB#431600, 431601,431603,431604,431606,431607,431608CB #431609,432613,432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTALCB#431602,431605,432614 AND 431499 ARE OPEN CURB PIECECATCH BASINS FOUR (4) IN TOTALCB#431601,431602,431603,431604,431605,431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO)STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLESCB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603,431604,431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFFAND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAYINSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463CLEANED FOUR (4) BASINS TO THE BOTTOMFUNCTIONING OTHERS C.O.B. AT THIS TIMEINSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463REPAIR BASIN NO.431608 AT 48 ST AND 37 AVEREMOVE ASPHALT AND OLD CASTING INSIDE UNITNO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORKINSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATERINSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334BOLOGNA TRK#464CLEANED BASIN NO.431605 TO THE BOTTOM FUNCTIONINGNO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M.INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464CLEANED BASIN NO.431604 TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM



Report Date: Tuesday, April 30, 2019

Page 3 of 3

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONING INSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATION FLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUE INSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABS VACTORED M/H#4015054-TO-M/H#4018279 850 FT NO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOT NEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTION INSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50 SUPV: G. PETRUSO TR# 315 CREW: SCHWEIZER/FANA TR# 004 SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/O NORTHERN BLVD B/T 42 ST & 44 ST NO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: There are no Safety Messages for this asset's Activity Code

Asset Safety Messages: There are no Safety Messages for this asset



WO# 844326029

Non-Completed Storm Inlet Work Order

Report Date: Tuesday, April 30, 2019

Page 1 of 3

Work Order#	844326029	Activity: SA25	REPAIR CONNECTION	
Address:	48 ST		Pct: 114	Zip: 11101
Cross Street:	37 AVE			
Compass Direction:			Borough: QUEENS	
Building ID:	0	Block:	Lot:	CMBD: 401
Storm Inlet ID:	CB431607			
Address:	48 ST			
Qualifier:	ON 0 FROM 37TH AV 37TH AV/BARNETT AV			Map# QI137
Area:	4	4	Sub-Area: 401 QUEENS COMMUNITY BOARD 1	
Location :	Asset Location Comments: ON 0 FROM 37TH AV 37TH AV/BARNETT AV		District: 844326029	
	ON 0 FROM 37TH AV 37TH AV/BARNETT AV			
Initiated By:	5425	PORCELLO, LOUISE A	Initiated: 04-23-2019 03:52 PM	Scheduled: N/A
Assigned To:			Service# 186596855	Due: N/A
Authorization:				
Crew:				
Maint Type:				
Priority:				
Problem:				Permit#
Project:				Completed: N/A
Source:				Out of Service: N
				Potential Service Request: N
WO Responsibility:	SEC	SEWER EMERGENCY CONSTRUCTION		

Work Order Log History				
Log Type	Log Started	Log Ended	Log By	Comments

There are no user logs for this work order

Primary Caller Information	
Primary Caller:	DEP, ABRUSI
Address:	
Day Phone:	(718)595-5816
Comments:	CREATED FOR THE YARD - INVESTIGATE THE AREA

Call Date: 07-02-2018 05:15 PM

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
INITIAL	07-05-2018	07-05-2018	7060-YAP, RICHMANN	Yap/Rivera veh#261During heavy rain fall (6-28-18), intersection of 48St & 37Ave flooded. Request cmom televise combined sewer to determine if combined line is adequate enough to take all that rain fall from so many catch basins attached to it. Input By: LINDA BUSH on 7/6/2018 3:01:55 PM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	48 ST BTWN 37 AND BARNETT AVES07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#464/593ARRIVED AT LOCATION AND INSPECTED FOURTEEN (14) CATCH BASINS ON 48 ST FROM 37 AVE TO BARNETT AVECB#431600, 431601,431603,431604,431606,431607,431608CB #431609,432613,432615 AND 431499 ARE SINGLE HIGHWAY UNITS WITH NO CURB PIECE ELEVEN (11) IN TOTALCB#431602,431605,432614 AND 431499 ARE OPEN CURB PIECECATCH BASINS FOUR (4) IN TOTALCB#431601,431602,431603,431604,431605,431606 AND 431607 HAD DEBRIS SITTING ON TOP OF GRATE BLACK TOYOTA PRIUS (SHOWN IN E-MAIL PHOTO)STILL PARKED OVER CB#431604 WITH PASSENGER BACK TIRE SITTING OVER GRATE AND BLOCKING DRAINAGE HOLESCB#431605 HAD CARDBOX (CARTON BOX) Input By: ANTHONY A PETERS on 7/19/2018 10:34:54 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CLEANED TO THE BOTTOM SIX (6) CATCH BASINS FLUSHED SIX (6) BASIN CONNECTIONS ALL TAKING WATERAND CLEAN AND CLEARCB CONN NO.431601 LINER IS DETACHED FROM CROWN OF PIPE APPROX 2 FT FROM CATCH BASIN FLUSHER WAS ABLE TO RE-OPEN NOW FUNCTIONING (STILL NEEDS TO BE REPAIRED) REMOVED ABOUT TWO (2) CUBIC YARDS OF DEBRIS FROM FIVE (5) CATCH BASINS WORK TO CONTINUEINSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 10:46:46 AM
INITIAL	07-03-2018	07-03-2018	5325-PETERS, ANTHONY	07/03/2018 0800-1205 YAP VEH#261FURCI-BULLOCK-THOMAS TRK#593/464CB#431605 HAD CARDBOX (CARTON BOX) COVERING PORTION OF GRATE PROBED ABOVE MENTIONS CATCH BASINS RELATIVELY CLEAN WORK TO CONTINUE AS BASINS BECOME ACCESSIBLE RECOMMEND CB#431603,431604,431606 AND 431607 BR REVERTED BACK TO CATCH BASINS WITH OPEN CURB PIECE TO ALLOW EXCESSIVE WATER FLOW TO EXIT INTO BASINS DURING HEAVY RAINFALL ALSO RECOMMEND L.I.R.R. ADDRESS WATER RUN-OFFAND GRAVEL DEBRIS THAT ESCAPE FROM THEIR EMBANKMENT AND GATED ACCESS WAYINSPECTION COMPLETE 7.19.18 1115 AP INSPECTION COMPLETE 7*19*2018 1047 AP Input By: ANTHONY A PETERS on 7/19/2018 11:15:54 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 0825-1015 MUNIZ trk#463CLEANED FOUR (4) BASINS TO THE BOTTOMFUNCTIONING OTHERS C.O.B. AT THIS TIMEINSPECTION COMPLETE 7.19.18 1133 AP Input By: ANTHONY A PETERS on 7/19/2018 11:37:28 AM
FOLLOWUP	07-05-2018	07-05-2018	5325-PETERS, ANTHONY	07-05-2018 1015-1315 MUNIZ trk#463REPAIR BASIN NO.431608 AT 48 ST AND 37 AVEREMOVE ASPHALT AND OLD CASTING INSIDE UNITNO PARKING REGULATIONS SEND WORK ORDER TO Q/REPAIRS FOR MINOR BRICKWORKINSPECTION COMPLETE 7.19.18 1148 AP Input By: ANTHONY A PETERS on 7/19/2018 11:49:36 AM
FOLLOWUP	07-06-2018	07-06-2018	5325-PETERS, ANTHONY	07-06-2018 0850-0910 FURCI-RIVERA TRK#804CHECKED AREA NO FLOOD WATER AT THIS PRESENT TIME DURING RAIN EVENT ALL BASINS TAKING WATERINSPECTION COMPLETE 7.19.18 1154 AP Input By: ANTHONY A PETERS on 7/19/2018 11:55:02 AM
FOLLOWUP	07-09-2018	07-09-2018	5325-PETERS, ANTHONY	07/09/2018 1140-1210 MARINELLI TRK#334BOLOGNA TRK#464CLEANED BASIN NO.431605 TO THE BOTTOM FUNCTIONINGNO SANITATION SWEEPER SHOWED LEFT AT 12:10 P.M.INSPECTION COMPLETE 7.19.18 1200 AP Input By: ANTHONY A PETERS on 7/19/2018 12:00:57 PM
FOLLOWUP	07-10-2018	07-10-2018	5325-PETERS, ANTHONY	07/10/2018 1225-1315 BOLOGNA TRK#464CLEANED BASIN NO.431604 TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1205 AP Input By: ANTHONY A PETERS on 7/19/2018 12:06:41 PM



Report Date: Tuesday, April 30, 2019

Page 3 of 3

Custlog History				
Log Type	Log Started	Log Ended	Log By	Comments
FOLLOWUP	07-11-2018	07-11-2018	5325-PETERS, ANTHONY	07/11/2018 1110-1145 BOLOGNA TRK#464CLEANED BASIN TO THE BOTTOM FUNCTIONINGINSPECTION COMPLETE 7.19.18 1232 AP Input By: ANTHONY A PETERS on 7/19/2018 12:30:45 PM
FOLLOWUP	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	07/19/2018 1050-1145 ABRUSCI VEH#525CAMPBELL-SALERNI TRK#593MET WITH FLUSHER CREW AT LOCATIONFLUSHED THREE BASIN CONNECTIONS NO.431602, 431601 431607 ALL THREE FUNCTIONING INSPECTED 18-INCH COMBINED SEWER ON 48 ST FROM 37 AVE TO NORTHERN BLVD FOUND DEBRIS IN SEVERAL MANHOLES VACTOR WORK NEXT WORK TO CONTINUEINSPECTION COMPLETE 7.19.18 1245 AP Input By: ANTHONY A PETERS on 7/19/2018 12:46:25 PM
CORRECTION	07-19-2018	07-19-2018	5325-PETERS, ANTHONY	SEE OPEN W/O#844166954 TO REPAIR BASIN CONNECTION Input By: ANTHONY A PETERS on 7/19/2018 3:16:14 PM
FOLLOWUP	07-24-2018	07-24-2018	5325-PETERS, ANTHONY	07.24.2018 0700-1500 MARINELLI TRK#334PRIVATE CONTRACTOR VACTOR WITH 2-LABSVACTORED M/H#4015054-TO-M/H#4018279 850 FTNO GREASE ONE CUBIC YARD OUTGOING PIPE IN M/H#4015055 IS SLIGHTLY HIGHER THAN INCOMING PIPE MAYBE 3" CAUSING MINOR HOLDING BUT NOT ENOUGH TO CAUSE PROBLEM COULD BE OVERTAXING IN M/H#4015054 DUE TO FIVE (5) CONNECTIONS COMING IN PLUS WATER FROM BASIN ON HOME DEPOT PROPERTY (NOT ON MAP) OVERFLOWING INTO STREET AND ENTERING OUR BASIN NO.461607 SPOKE TO ANDREW (HOME DEPOT MANAGER) TO HAVE CATCH BASIN CLEANED NEED E.C.B. OR RESPONSIBLE AGENCY TO FOLLOW UP WITH HOME DEPOTNEED CMOM TO INVESTIGATE OVERTAXING OF M/H#4015054 AND/OR FEASIBILITY STUDY FOR INSTALLATION OF BIOSWALES TO REDUCE FLOW SEWER IS CLEAR NO OBSTRUCTIONINSPECTION COMPLETE 7.25.18 0917 AP Input By: ANTHONY A PETERS on 7/25/2018 9:18:29 AM
FOLLOWUP	02-07-2019	02-07-2019	1193-ANZUETA, JOSEPH	Anzueta veh#37748St. - 37Ave n/w/c chute connection working improperly need to upgrade and repair same. Refer to Sewer Emergency Reconstruction. Input By: LINDA BUSH on 2/8/2019 8:08:04 AM
FOLLOWUP	02-13-2019	02-13-2019	6050-SCHWEIZER, JAMES	02/13/19 13:05-13:50SUPV: G. PETRUSO TR# 315CREW: SCHWEIZER/FANA TR# 004SOUNDED HYDRANT ON W/S/O 42 ST 1ST N/O NORTHERN BLVD NO NOISE HYDRANT ON S/S/O NORTHERN BLVD 20' E/O 42 ST NO NOISE NO MAIN ON N/S/ONORTHERN BLVD B/T 42 ST & 44 STNO FURTHER ACTION Input By: EVELYN HOPSON on 2/14/2019 6:55:57 AM

Activity Safety Messages: There are no Safety Messages for this asset's Activity Code

Asset Safety Messages: There are no Safety Messages for this asset